Safe Routes to School Program

Terrill Middle School Travel Plan

1301 Terrill Road Scotch Plains, NJ 07076



Prepared By:

Meadowlands Transportation Brokerage Corporation

d/b/a Meadowlink 144 Park Place East Wood-Ridge, NJ 07075 (201) 939-4242 www.ezride.org

July 25, 2016



DISCLAIMER

This publication was prepared with funding from the New Jersey Department of Transportation (NJDOT) and the Federal Highway Administration (FHWA). This document is disseminated under the sponsorship of NJDOT and FHWA in the interest of information exchange. NJDOT and FHWA assume no liability for its contents or use thereof.











Table of Contents

Executive Summary	3
1. Walking and Cycling to Health	5
1.1 The Challenge	5
1.2 The Program	5
1.3 The Team and Taskforce6	õ
2. District & School Profile	9
2.1 Scotch Plains – Fanwood Health Profile1	L O
2.2 Terrill Middle School	14
3. Journey to School	ا6
3.1 Current Student Travel Environment	17
3.2 Pedestrian Safety	18
3.3 Walkability Audit	19
4. Action Plan & Recommendations	' 3
Appendices	
Appendix A: How to Approach Residents that Contest Sidewalk Installation7 Appendix B: Typical Opportunities for Improvement	

Executive Summary

A Safe Routes to School (SRTS) Travel Plan is a resource to encourage and increase the number of students walking or bicycling to school. It provides directions for schools, students, families and the city to build a safer walking and biking environment for residents.

School Travel Plans are site specific and describe the needs of each particular school being studied. The plan includes observations, ideas and an action plan to address issues and problem areas. The Plan covers five aspects of the Safe Routes to School program – Education, Encouragement, Enforcement, Evaluation, and Engineering.

The School Travel Plan outlines the timeframe and funding priorities to support a coordinated schedule of streetscape improvements. In fact, the New Jersey Safe Routes to School (SRTS) infrastructure funding program strongly recommends applicants to have an approved School Travel Plan in order to apply for a grant.

1. Goals

The goals of the Terrill Middle School Travel Plan are:

- a. Identify any issues that impact safety on the key travel routes used by students
- b. Provide a list of suggestions to improve the safety of the travel environment around school
- c. Prioritize the suggestions in terms of cost and time needed to make improvement.
- d. Propose solutions to encourage more students to walk and bike to school

2. Task Force

This School Travel Plan is the product of a robust and productive partnership. The Terrill Middle School SRTS Task Force came together out of a shared community interest in improving the lives of students and residents. The involvement of local stakeholders is an important part of ensuring the sustainability of the SRTS initiative and the enactment of the Action Plan.

3. Community Barriers to Health

In May 2016 a Parent/Caregiver questionnaire was distributed. Parents of Scotch Plains' children, age three to eighteen, were surveyed to identify their top concerns with students walking or biking to school. The concerns identified by parents include:

- a. Unpleasant sidewalks that are in disrepair
- **b.** Unsafe intersections as crosswalks are absent
- c. Property owners' plants encroaching into sidewalks
- **d.** Traffic congestion near schools during drop off and pick up

4. School Travel Data

In May 2015, Terrill Middle School teachers conducted a School Travel Tally to determine how students travel to and from school.

Typically 7 percent of students walk to school, 46 percent of students are driven to school, 17 percent carpool, 30 percent use the school bus, and only 1 percent of students ride bicycles to school.

5. Barriers and Opportunities Identified for Safer Walking & Biking

The Safe Routes to School Taskforce and Community Partners conducted a detailed walkability assessment of the road conditions along the main routes used by the students to walk to school on May 19, 2016. The major intersections surrounding the school are Terrill Road and Cooper Road and Raritan Road and Martine Avenue.

Key opportunities for bicycle and pedestrian infrastructure improvement around Terrill Middle School include: painting new high visibility crosswalk striping, repainting crosswalk striping, painting Stop sign bars, adding truncated dome pads and curb ramps to meet American with Disabilities Act (ADA) compliance, repaving sidewalks, and installing new sidewalks.

6. Action Plan

The Safe Routes to School program categorizes the Action Plan into the "Five E's:" Education, Encouragement, Enforcement, Evaluation and Engineering. This is a useful tool because it helps the school prioritize next steps. In a particular community, some of the action items may be more urgently needed than others, so the school can execute the recommendations in any order they choose. This School Travel Plan recommends a number of improvements that can be made to encourage safe walking and biking. The action plan can be used to support SRTS and other Federal or State grant applications to fund pedestrian and bicycle improvements.

Key Actions/Recommendations in Action Plan include:

- Repave and level/resurface sidewalks along Kevin Road, King Street, Terrill Road, Cooper Road,
 Coles Elementary Bike Path, Terrill Middle School Bike Path, Raritan Road, & West Broad Street
- Paint/repaint high visibility crosswalks at: Cooper Road & Terrill Road, King Street & Martine Avenue, King Street & Terrill Road, Kevin Road in front of Coles Elementary, Colonial Drive & Terrill Drive, and Graymill Drive & West Broad Street
- Install a curb ramp for the bike path behind Cole Elementary
- Install bike racks behind Terrill Middle School
- Paint Bike Lanes on Raritan Road, Terrill Road, and Cooper Road
- Install new sidewalks, curb ramps, truncated dome pads, along majority of the routes, roads, and intersections
- Paint crosswalks and stop sign bars at most of the intersections along routes

1. Walking and Cycling to Health

1.1 The Challenge

Over the past few decades, a number of societal and environmental changes have limited children's access to safe places where they can walk, bike and play. For example, increased traffic, neighborhoods that lack sidewalks and urban sprawl have contributed to a sharp decline in the number of students who walk or bike to school. Nationally, while 42 percent of children walked or biked to school in 1969, only 13 percent of children did so in 2001. Additionally, the popularity of television and video games as a means to entertain children has contributed to a more sedentary lifestyle. As a result, children and adolescents are less physically active than they were several generations ago.

The decrease in walking and biking to school and less physical forms of play has resulted in an alarming increase in childhood obesity. During the past four decades, the obesity rate for children ages 6 to 11 has more than quadrupled (from 4.2 to 17 percent), and the obesity rate for adolescents ages 12 to 19 has more than tripled (from 4.6 to 17.6 percent).

Developing policies and practices to address these environmental and social barriers to daily physical activity are critical to reducing and preventing obesity among children. Supporting "active transport" (or walking and bicycling) to school presents an excellent opportunity to increase daily physical activity among youth.¹

1.2. The Program

Safe Routes to School (SRTS) is a federal program that encourages, teaches, and enables children to safely bicycle and walk to school. The program aims to help children be more physically active with the intent to reduce chronic disease and prevent and reduce obesity. SRTS focuses on increasing the number of children walking and bicycling to school by building and repairing infrastructure such as sidewalks, crosswalks, and bicycle lanes. The program also encourages changes in travel behavior, supports increased enforcement of traffic laws around schools, and educates communities on the benefits and safety aspects of active transport. This report summarizes research on active transport to school. It also explores the factors that influence walking and biking to school, including the impact of SRTS programs.

The SRTS Program is a collaborative effort of multiple stakeholders that include community members, elected officials, city planners, and police departments. SRTS brings a community closer together by implementing programs such as walking school buses, walkability audits, bicycle rodeos and pedestrian safety presentations. The benefits of SRTS extend far beyond the schools into the community as a whole.

¹ Walking and Biking to School, Physical Activities and Health Outcomes, Robert Wood Johnson Foundation

A SRTS School Travel Plan "maps out" specific ways to improve pedestrian and bicycle travel to increase the number of students who walk and bike to school and to improve safety. A School Travel Plan identifies the following:

- Where students currently walk and bike?
- Where students would walk and bike if they could?
- What changes need to be made so that students can and will walk and bike to school?

The School Travel Plan identifies short term solutions for immediate action and implementation as well as long term solutions that may require planning and additional funds. Benefits of developing a School Travel Plan include:

- Creating partnerships between the school and surrounding community
- Generating ideas and actions so walking and bicycling is safer
- Building community excitement and support
- Making an application for a SRTS grant more competitive by demonstrating a connection between goals, actions and targets.

1.3. The Team

The New Jersey Department of Transportation (NJDOT) funds and administers the SRTS program in New Jersey, and the Voorhees Transportation Center (VTC) at Rutgers' University provides technical and administrative support.

The actual implementation of the SRTS program at the Terrill Middle School was undertaken by two organizations – EZ Ride and the Fanwood-Scotch Plains YMCA.

EZ Ride

In New Jersey, Transportation Management Associations (TMAs) have taken the lead in coordinating the implementation of the SRTS programs. TMAs are non-profit organizations whose mission is to implement transportation programs and services like carpools, vanpools, shuttles, biking and walking that reduce congestion and improve air quality. EZ Ride is one of eight Transportation Management Associations (TMAs) in New Jersey and primarily serves Bergen, Essex, Monmouth, Passaic and Union counties.

Fanwood-Scotch Plains YMCA

The Fanwood-Scotch Plains YMCA is a leading voice within the community on health and well-being, with a mission centered on balance and developing connection with individuals and families. The YMCA supports the community by providing opportunities to build and sustain life-long habits of health. It provides resources to children, adults and families by developing small communities of support within various areas. Health enhancement programs are designed to help people develop new skills through active lifestyle, proper nutrition, stress management and health education aimed at empowering individuals to choose healthier options. The YMCA is dedicated to addressing the chronic disease challenges within the community and developing programs and strategies aimed at

improving overall health. The YMCA is committed to serving the underserved and developing partnerships to help support those needs.

Township of Scotch Plains

The township decided to apply for the SRTS infrastructure grant. A township full-time employee and the Town engineer are working with the resource support of EZ Ride and Voorhees Transportation Center to write and submit the grant application.

Scotch Plains-Fanwood PTA

The PTA has been supportive of SRTS efforts including the Walk to School Day and bringing Walking Safety programs into the schools. A PTA leader helped with the walkability assessment.

Terrill Middle School Travel Plan Task Force

Organization	Role/Responsibility	Contact				
Terrill Middle School	Program Activity and	Dr. Kevin Holloway,				
	Implementation	Principal				
		1301 Terrill Road,				
		Scotch Plains, NJ, 07076				
		(908) 322-5215				
		kholloway@spfk12.org				
SRTS Champion	Program Activity and	Gina Giacona				
	Implementation	Scotch Plains-Fanwood PTA				
		Health & Wellness Council Chair				
		1301 Terrill Road,				
		Scotch Plains, NJ, 07076				
		ginatmspta@yahoo.com				
Fanwood-Scotch Plains YMCA	Program Activity and	Jennifer Donahue				
	Implementation	Terrill Middle PTA				
		Health & Wellness Representative				
		1340 Martine Avenue				
		Scotch Plains, NJ 07076				
		(908) 889-8880 x115				
		idonahue@fspymca.org				
Fanwood-Scotch Plains YMCA	Program Activity and	Sheri Cognetti				
	Implementation	YMCA Senior Program Director				
		1340 Martine Avenue				
		Scotch Plains, NJ 07076				
		908-889-8880 ext. 114				
		scognetti@fspymca.org				

Scotch Plains Township	Town liaison, Grant	Margaret Heisey				
Scotch Hams Township	writing	HR, Program Management				
	Wilchig	430 Park Avenue				
		Scotch Plains, NJ				
		908-322-6700				
		mheisey@scotchplainsnj.com				
Scotch Plains Township	Engineering Project	Joseph Timko				
	Implementation	Assistant Engineer				
		430 Park Avenue				
		Scotch Plains, NJ				
		908-322-6700, ext. 306				
EZ Ride -	SRTS Program	Mateusz Pitrus				
Transportation Management	Assistance,	Safe Routes to School Asst. Coordinator				
Association	Community Resource,	EZ Ride				
	Safety Education	144 Park Place East				
	,	Wood-Ridge, NJ 07075				
		201-939-4242 ext. 122				
		mpitrus@ezride.org				
Alan M. Voorhees Transportation	Web- based	Leigh Ann Von Hagen, AICP/PP				
Center	resources, Technical	Senior Research Specialist				
	Assistance, SRTS	Alan M. Voorhees Transportation Center				
Edward J. Bloustein School of	Recognition Program,	Edward J. Bloustein School of Planning				
Planning and Public Policy, Rutgers	Helpdesk assistance,	and Public Policy				
The State University of New Jersey	SRTS Tools, Tips and	Rutgers, The State University of NJ				
The State Offiversity of New Jersey	Training	33 Livingston Avenue				
	Training	-				
		New Brunswick, New Jersey 08901				
		848-932-2854				
NI DOT	Const. F. and C. C. C.	lavh@ejb.rutgers.edu				
NJ DOT	Grant Funding, State	Elise Bremer-Nei, AICP/PP				
	SRTS Resource. SRTS	State Safe Routes to School Program				
	Best Practices	Coordinator				
		NJ Department of Transportation				
		Office of Bicycle and Pedestrian Programs				
		P.O. Box 600				
		Trenton, NJ 08625-0600				
		609-530-2765				
		elise.bremer-nei@dot.nj.gov				

2. District & School Profile

A school profile for Terrill Middle School was developed using data from the Scotch Plains – Fanwood District website, the Terrill Middle School website, and the National Center for Education Statistics. Additional site-specific information was collected from parent surveys, interviews and onsite visits.

The Township of Scotch Plains and the Borough of Fanwood are attractive residential communities located in north central New Jersey. The Scotch Plains-Fanwood Public Schools serve approximately 5,500 students from Preschool – Grade 12. The district offers a comprehensive academic program, excellent pupil services, an experienced and highly qualified staff, modest class size (12.98:1 student to teacher ratio), and a wide variety of extracurricular athletics and activities. The district has five elementary schools (Preschool – Grade 4), 2 middle schools (Grades 5-8), and one comprehensive high school (Grades 9-12). Student demographics are shown in Table 1 below.

Table 1. Scotch Plains – Fanwood Public Schools – Student Demographics

Ethnicity	f of Students
African-American	497
Hispanic	380
Caucasian	3,988
Asian/Pacific Islander	471
American Indian/Native American	9
Two or More Races	136
Gender	# of Students
Male	2,736
Female	2,745
Grade Level	# of Students
Primary (Pre-Kindergarten – Grade 4)	2,101
Middle School (Grade 5 - 8)	1,756
High School (Grade 9 - 12)	1,551
Special Needs Students/Individualized Education Program	n 73

Academic Performance

According to the New Jersey Department of Education data, Scotch Plains-Fanwood public schools are rated highly in academic performance when compared with other schools in the state. Schools are also compared to a group of schools that have similar student demographic characteristics (such as free/reduced lunch eligibility), known as a peer group. Across all the schools, the High School ranked lowest in terms of percentage of students meeting or exceeding expectations in math and language arts but still were in the 90th (peer) and 87th percentile (state). The elementary and middle schools had majorities of students meeting or exceeding expectations; 62 percent for math and 71

percent for language arts. Compared to their peers, they were never lower than the 68th percentile and not lower than the 86th percentile when compared to the entire state.

The Scotch Plains – Fanwood School district is classified by the NJ Department of Education as District Factor Group "I," the second highest of eight groupings, indicating an advantaged community. A District Factor Group (DFG) is an indicator of the socioeconomic status of citizens in school districts of New Jersey. DFGs were first developed by the New Jersey Department of Education in 1975 for the purpose of comparing student performance on statewide assessments across demographically similar school districts.

2.1. Scotch Plains – Fanwood Health Profile – Union County Community Health Assessment


In 2016, the North Jersey Health Collaborative worked with the Center of Population Sciences and the Atlantic Health System to conduct a Community Health Assessment of Union County. The North Jersey Health Collaborative is a 501(c)3 organization with over 120 partner organizations aligned around shared goals for collective impact. In 2015, the Collaborative conducted a year-long process of community-based assessment entitled "Painting a Picture of Community Health". Throughout this process, 107 community leaders participated from 56 organizations representing 12 community sectors. After data were collected, three data review sessions were held in Union County and a total of 125 issues were identified.

Understanding Social Determinants of Health

Conditions in the places where people live, learn, work, and play affect a wide range of health risks and outcomes. These conditions are known as social determinants of health. We know that poverty may limit healthy food access and coincide with unsafe neighborhoods and that more education is a predictor of better health. We also know that differences in health are striking in communities with poor social determinants of health such as unstable housing, low income, unsafe neighborhoods, or substandard education. By applying what we know about social determinants of health, we can not only improve individual and population health but also advance health equity.


Source: Centers for Disease Control and Prevention

Chart 1: Poverty Level 2015



Source: 2016 Community Needs Assessment Union County; US Census Bureau: Income and Poverty Estimates


Chart 2: Estimated Median Household Income – Scotch Plains – Fanwood, NJ



Source: 2016 Community Needs Assessment Union County; US Census Bureau: Income and Poverty Estimates (2011-2015)


Chart 3: Income Households by Type – Scotch Plains, NJ

Percentage of Scotch Plains Household types



City-Data.com, 2013

Chart 4: Income Households by Type – Fanwood, NJ Percentage of Fanwood Household types



City-Data.com, 2013

Approximately 1 in 5 households in Scotch Plains and Fanwood are run by a single parent. This is lower but follows a similar trend throughout New Jersey. As shown in Chart 4, in the past decade the percent of single – parent households has increased from 31.8 percent to 33.3 percent.

Single-Parent Households - Change over Time County: Union | Source: American Community Survey (2010-2014) 34 33.3% 33 32.7% percent 32.4% 32.2% 31.8% 32 31 2007-2011 2008-2012 2009-2013 2010-2014 2006-2010

Chart 4: Single – Parent Household Trend in Union County

Source: NJHealthmatters.org; American Community Survey

Childhood Obesity

Between 2009 – 2011 19.3 percent of low income preschool aged children in Union County reported as obese. The trend appears to be on the decline in recent years as it was reported that 21.3 percent of low-income preschool aged children were obese when data was collected in 2006 – 2008.

Adult Obesity

In 2013, data collected showed that 24.7 percent of Union County adults over the age of 20 were obese. This is a slight increase from a previous reported value of 24.5 percent.

Media Viewing Habits

The American Academy of Pediatrics recommends that children spend a maximum of two hours per day on entertainment media like television, computers, and video games.

Exercise

The HHS 2008 Physical Activity Guidelines for Americans recommend that adults get at least thirty minutes of moderate to vigorous activity daily and that children get at least sixty minutes of moderate to vigorous physical activity daily.

2.2 Terrill Middle School

Terrill Middle School strives to educate and empower the community of individual learners to be successful citizens of the world. The educators of Terrill Middle School, with parents as partners, are highly committed to pursuing and maintaining an academically excellent, developmentally responsive, and socially equitable learning environment for every student.

The academic program at Terrill Middle School currently provides two distinctive instructional models across four grade levels. The fifth grade instructional program is primarily a self-contained environment with a strong emphasis on mathematics, language arts literacy, science, and social studies. In addition to these core subjects, students experience three world languages, fine arts, and physical education/health. The sixth, seventh, and eighth grade instructional programs are structured on a team concept. In addition to the exceptional academic core program, students explore art and music. World language is included in the sixth grade curriculum as students make a three-year commitment to build proficiency in French, Italian, or Spanish. Finally, in all grade levels students may elect to participate in our outstanding music program through band and/or chorus.

Students may also participate in clubs and after school activities such as: Art Club, Intramural Club, Homework Club, Jazz Band, newspaper, a musical production, drama club, Builder's Club, PALS (Peer and Leadership Support), student council, and yearbook.

With excellence, initiative, and diversity as our cornerstones, we commit ourselves to providing exceptional learning experiences for all students.

Terrill Middle School serves approximately 825 students in Grade Five to Grade 8. As Chart 7 below shows, about 73 percent of the students enrolled are Caucasian, 7 percent are Hispanic, 7 percent are African American, 10 percent of students are Asian, and 3 percent of students are Two or More Races.




Chart 1: Terrill Middle School Enrollment by Student Ethnicity in 2014 – 2015

New Jersey School Performance Report. 2014-2015. http://www.nj.gov/education/pr/1415/39/394670065.pdf

The number of students has slightly decreased from 845 in 2012 to 825 in 2013 and 2014. As shown in Table 2 below, English is the dominant language spoken at home by a wide margin at 93.6 percent of the students at home. Chinese is spoken by 1.9 percent of students in their homes. Spanish is spoken by 0.8 percent by students in their home. Hindi is spoken by 0.7 percent. Gujarati is spoken by 0.5 percent. Telugu is spoken by 0.4 percent. Finally, 2.0 percent identify "Other" as a language spoken at home.

Table 2. Student Language Diversity (2014 – 2015)

Language Diversity								
Percent of students who speak the following languages at home								
English 93.6%								
Chinese	1.9%							
Spanish	0.8%							
Hindi	0.7%							
Gujarati	0.5%							
Telugu	0.4%							
Other	2.0%							


 $New \ Jersey \ School \ Performance \ Report. \ 2014-2015. \ http://www.nj.gov/education/pr/1415/39/394670065.pdf$

3. Journey to School

In the 1960s, about 50 percent of children in the United States walked or bicycled to school. Over the last few decades, concerns about vehicle traffic, safety for the children, and longer commutes have forced more and more parents to drive their children to school. This results in more traffic on the road and less children who walk to school. Today, on average only about 15 percent of children walk or bike to school. Map 1 provides a broad overview of the residential area near Terrill Middle School.

Map 1: Two Mile Radius around Terrill Middle School

Map 1 shows a two-mile radius surrounding the school. The neighborhood is in close proximity to a Golf Course and a Country Club. The district is split by County Road 28.





Terrill Middle School

3.1. Current Student Travel Environment

School Hours

The school day for students starts at 8:10 am and the day ends at 2:40 pm Monday through Friday. Students can attend extended learning programs at the school through after school programming Monday through Friday until 3:30 pm. There are no late buses provided for students after these programs.

Drop-off/Pickup Procedure

Buses drop off and pick up students directly in the front of the school's entrance. Parents drop off and pick up students in two locations: 1) by the curb on Terrill Road in front of the school or 2) at the adjacent church parking lot.

Crossing Guards

A crossing guard is stationed at the intersection of Kevin Road and Terrill Road, near the adjacent church.

Student Travel Mode

In May 2015, the teachers at Terrill Middle School conducted a SRTS Student Travel Tally Survey to document how the children in their classes get to and from school. Tallies were taken by teachers three times during one week. A total of 4,054 trips were documented and the data was analyzed by the NJ Safe Routes to School Resource Center at the Voorhees Transportation Center, Rutgers University.

As shown in Table 3, the analysis found that about 7 percent of children walk to school, 46 percent of the trips to school were in personal cars, 17 percent of students carpooled to school, 30 percent took the school bus, and 1 percent biked to school. 18 percent of students reported walking home, 36 percent were driven home, 28 percent took the school bus home, 16 percent carpooled home, and 1 percent biked home.

Table 3. Current Commute Mode

Mode	Arrival	Dismissal			
Walk	7 percent	18 percent			
Driven in personal car	46 percent	36 percent			
School Bus	30 percent	28 percent			
Carpool	17 percent	16 percent			
Bike	1 percent	1 percent			









3.2 Pedestrian Safety

EZ Ride conducted an analysis of the pedestrian-related crashes within a one-mile radius of the school over a 12-year period from 2003 to 2015 based on police incident reports. The reported incidents were plotted on Map 2.

Fanwood 🛅 A. Evangel Church Terrill Middle School Parker Gardens

Map 2: Pedestrian Crashes within One Mile of Terrill Middle School, 2003-15



Terrill Middle School



Pedestrian Crash Location

Table 4. Pedestrian Crashes by Age, In Scotch Plains Township (2003-2015)

Age	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	Total	Percent
0-10	1	0	1	1	0	1	0	0	0	0	0	0	2	6	8%
10-17	1	0	0	2	2	1	0	1	1	1	1	0	3	13	17%
18-35	1	1	1	1	1	0	3	2	3	1	1	2	2	19	25%
36-60	2	2	0	3	4	3	2	0	1	2	2	0	2	23	30%
60+	0	1	2	2	1	1	2	0	3	1	1	0	2	16	21%
Total	5	4	4	9	8	6	7	3	8	5	5	2	11	77	

For Scotch Plains Township, there were 77 pedestrian crashes between the years 2003-15. On average, Scotch Plains Township had approximately 6 pedestrian crashes per year. While the majority of the crashes (55 percent) involved pedestrians aged 18-60, about 25 percent (19) of the total incidents involved children in the 0-17 age group. Last year in 2015, the pedestrian crashes were the highest the town has seen in 12 years with 11, an average of nearly 1 pedestrian crash per month. Children under 17 accounted for approximately 45% (5) of pedestrian crashes in 2015.


3.3 Walkability Assessment

The SRTS Task Force conducted a walkability assessment of the major routes used by students to get to Terrill Middle School. School children and residents of all ages and abilities walk in and through the neighborhood. Map 3 below shows the walking routes which were assessed in the audit.

A Walkability Assessment evaluates the sidewalks, roads, crosswalks, lighting, signs, signals, and conditions of the walking environment along the walking route. A walkability assessment identifies pedestrian and bicycle infrastructure improvements that can be made and notes what is currently done well. The SRTS Taskforce took photos of areas on each route. Comments and recommendations are listed with each photo and are summarized in the Action Plan at the end.

Map 3, on the following page, shows all three of the walking routes which were assessed.

Map 3. Main Walking Routes





Terrill Middle School



Route 1

Route 2



Route 3




Route 4



Route 5

Map 4: Walking Assessment of Route 1:






Terrill Middle School



Walking South Kevin Road

Photo 1: Walking South on Kevin Road



- 1. Sidewalk broken, cracked, bumpy, and in disrepair
- 2. Sidewalk narrows
- 3. Sidewalk only on one side of road
- 4. Recommend repaving, leveling, and widening sidewalk
- 5. Recommend installing sidewalk on both sides of road

Walking South on Kevin Road by Coles Elementary

Photo 2: Walking South of Kevin Road by Coles Elementary



- 1. Area outside of Cole Elementary is in relatively good shape
- 2. Concrete Sidewalk seems to be much more resilient than asphalt
- 3. Curb and grass present to create separation from road and sidewalk
- 4. Recommend high visibility restriping of crosswalks
- 5. Recommend addition of School Zone Signs

Intersection of Kevin Road and Aberdeen Road


Photo 3: Intersection of Kevin Road and Aberdeen



- 1. Truncated domes missing
- 2. Curb ramp and sidewalk only on one side
- 3. Recommend installing truncated domes, curb ramp, and sidewalk on both sides

Intersection of Aberdeen Road and Highlander Drive

Photo 4: Intersection of Aberdeen Road and Highlander Drive



Observations

- 1. No crosswalks
- 2. No truncated dome pads
- 3. Stop bar missing
- 4. No sidewalks
- 5. Recommend installing curbs, truncated domes, and sidewalks
- 6. Recommend painting high visibility crosswalks and Stop bar

Walking Highlander Drive

Photo 5: Walking Highlander Drive



- 1. No sidewalks or curbs
- 2. No pedestrian lighting
- 3. Recommend installing sidewalks and pedestrian lighting

Intersection of Highlander Drive and Argyle Court

Photo 6: Intersection Highlander Drive and Argyle Court



- 1. No crosswalks
- 2. No sidewalks
- 3. No Stop Sign
- 4. Wide Turning radius which encourages speeding into turns
- 5. Recommend installing sidewalks, curb ramps, truncated domes, and Stop sign
- 6. Recommend painting high visibility crosswalk and Stop bar

Intersection of Highlander Drive and Clydesdale Road

Photo 7: Intersection of Highlander Drive and Clydesdale Road



- 1. Roadway is cracked and in need of repair
- 2. No crosswalks
- 3. No sidewalks
- 4. Stop bar missing
- 5. Recommend installing sidewalks
- 6. Recommend repaving road
- 7. Recommend painting high visibility crosswalk and Stop bar

Intersection of Highlander Drive and Heather Lane

Photo 8: Intersection of Highlander Drive and Heather Lane




- 1. No crosswalks
- 2. No sidewalks
- 3. No Stop sign
- 4. Wide turning radii
- 5. Recommend installing sidewalks
- 6. Recommend repaving road
- 7. Recommend painting high visibility crosswalk and Stop sign

Intersection of Heather Lane and Cooper Road

Photo 9: Intersection of Heather Lane and Cooper Road



- 1. No crosswalks
- 2. No sidewalks
- 3. No curb ramps or truncated domes
- 4. Stop bar faded
- 5. Recommend installing sidewalks, curb ramps, and truncated domes
- 6. Recommend painting high visibility crosswalk



Map 5: Walking Assessment of Route 2



Terrill Middle School



Intersection of King Street and Martine Avenue

Photo 10: Intersection of King Street and Martine Avenue



- 1. Crosswalk present
- 2. Truncated dome present on one side
- 3. Sidewalk ends on one side
- 4. Missing sidewalk, curb ramp, and truncated dome
- 5. Recommend installing sidewalk, curb ramp, and truncated dome
- 6. Recommend repainting crosswalk with high visibility striping

Walking Down King Street

Photo 11: Walking Down King Street



- 1. No sidewalks on either side
- 2. Intersections along King Street are almost all missing:
 - Crosswalks
 - Sidewalks
 - Curb ramps
 - Truncated domes
- 3. Recommend installing sidewalks, curb ramps, and truncated dome pads
- 4. Recommend painting high visibility crosswalks and Stop bars

Intersection of Tanglewood Lane and King Street

Photo 12: Intersection of Tanglewood Lane and King Street



- 1. Truncated domes are absent
- 2. Crosswalk absent
- 3. Stop bar missing
- 4. Sidewalks begins on King Street at this intersection on near side
- 5. Recommend installing truncated domes and curb ramps to meet ADA requirements
- 6. Recommend painting Stop bar
- 7. Recommend painting high visibility crosswalk
- 8. Recommend installing sidewalks

Sidewalk along King Street past Tanglewood Lane

Photo 13: Sidewalk along King Street past Tanglewood Lane



Observations and Recommendations

- 1. Sidewalks are broken, cracked, uneven, and narrow
- 2. Recommend repaving, leveling, and widening sidewalks to reduce tripping hazards

Sidewalk along King Street past Tanglewood Lane Photo 14: Sidewalk along King Street past Tanglewood Lane



Observations and Recommendations

- 1. Sidewalks are cracked, broken, uneven and in need of repair
- 2. Utility pipes/covers and holes present tripping hazards
- 3. Recommend repaving sidewalks and ensuring they are level
- 4. Recommend utility pipes/cover be level with sidewalk

Intersection of King Street and Terrill Road

Photo 15: Intersection of King Street and Terrill Road



- 1. Truncated domes present but not properly angled
- 2. Crosswalk present
- 3. Recommend painting high visibility crosswalk striping and rotating truncated domes pointed toward the crosswalk

Walking along Terrill Road toward Terrill Middle School

Photo 16: Walking along Terrill Road toward Terrill Middle School



Observations and Recommendations

- 1. Sidewalk is cracked, broken, uneven, and in need of repair
- 2. Recommend repaving sidewalk

Walking along Terrill Road toward Terrill Middle School

Photo 17: Walking along Terrill Road toward Terrill Middle School



- 1. Owner's vegetation extends into pedestrian walkway
- 2. Forces pedestrians to duck
- 3. Leaves and other debris could provide slipping hazards and makes walk less pleasant
- 4. Recommend having discussions with residents about maintaining their vegetation and keep it trimmed so as to not impede pedestrian path

Intersection of Terrill Road and Cushing Road

Photo 18: Intersection of Terrill Road and Cushing Road



Observations


- 1. Stop bar from Cushing Road is absent
- 2. No crosswalk in either direction
- 3. Shoulder lines, lane markers, faded along Terrill Road

Sidewalks along Terrill Road

Photo 19: Sidewalks along Terrill Road



- 1. Sidewalks broken, holes present, rocks/chunks of asphalt from broken driveway or sidewalk present tripping hazards, and generally in need of repair
- 2. Recommend repaving and leveling sidewalks



Map 6: Walking Assessment of Route 3



Terrill Middle School



Along Kevin Road by Coles Elementary

Photo 20: Along Kevin Road by Coles Elementary



- 1. Driveway exit from Coles Elementary Parking Lot
- 2. No Crosswalk
- 3. Truncated domes not facing intersection
- 4. Recommend painting high visibility crosswalk
- 5. Recommend installing Student/Pedestrian Crossing Signs

Along Kevin Road by Coles Elementary

Photo 21: Along Kevin Road by Coles Elementary



- 1. Entrance driveway to Coles Elementary Parking Lot
- 2. No crosswalk striping and truncated domes not facing intersection
- 3. Holes and uneven asphalt where students would cross
- 4. Recommend repairing/levelling asphalt, angling truncated domes properly, and painting high visibility crosswalk striping
- 5. Recommend installing Student/Pedestrian Crossing Signs

Coles Elementary School Parking Lot

Photo 22: Coles Elementary School Parking Lot



- 1. Coles Staff parking lot is frequently used as shortcut by Terrill Middle School students
- 2. Broken, uneven, and in need of re-pavement
- 3. Recommend installing signs to make drivers aware of potential students

Coles Elementary School Parking Lot

Photo 23: Coles Elementary School Parking Lot



- 1. Faded, angled, protected crosswalk present
- 2. Recommend high visibility re-striping
- 3. Recommend installing Student/Pedestrian Crossing signs to make drivers aware of crosswalk area

Coles Elementary School Blacktop

Photo 24: Coles Elementary School Blacktop



- 1. Coles Elementary School Blacktop, behind school
- 2. Students enter through bike path near back, cut through as shortcut to Terrill
- 3. Parent informed without any lighting it becomes dark and the area floods during rainstorms
- 4. Recommend installing pedestrian lighting
- 5. Recommend investigating potential drainage solution

Coles Elementary School Rear Bike Path

Photo 25: Coles Elementary School Rear Bike Path



- 1. Bike Path used by Terrill Middle School students
- 2. No lighting; can be dark and dangerous, especially during early morning hours
- 3. Asphalt is in disrepair, broken, and not level
- 4. Recommend adding pedestrian lighting
- 5. Recommend re-paving path

Coles Elementary School Rear Bike Path

Photo 26: Coles Elementary School Rear Bike Path



- 1. Broken, uneven, path in need of repair
- 2. Recommend re-paving path
- 3. No lighting makes the path hazardous in dark
- 4. Recommend installing pedestrian lighting

Allenby Lane Bike Path Entrance

Photo 27: Allenby Lane Bike Path Entrance



- 1. Bike path entrance from Allenby Lane
- 2. No curb cut/curb ramp
- 3. Not ADA compliant and hazard to students biking or walking
- 4. Recommend cutting the curb and adding a ramp

Allenby Lane towards Heritage Court


Photo 28: Allenby Lane towards Heritage Court



- 1. Allenby Lane leading to bike path
- 2. No sidewalk on either side of the street
- 3. No School Zone Signs
- 4. Resident informed of disregard for "No Parking During School Hours" sign as Coles Elementary parents park their cars to walk their children to school
- 5. Recommend installing sidewalks
- 6. Recommend installing "School Zone" signs
- 7. Recommend painting bike lane, sharrow, or signage to help protect students that use the bike path and raise awareness with drivers of children bikers
- 8. Recommend discussing with Scotch Plains Police Department to enforce "No Parking" Sign

Heritage Court towards Cooper Road

Photo 29: Heritage Court toward Cooper Road



- 1. Residential road connecting from Allenby Lane
- 2. No sidewalks on either side of the street
- 3. Cracked, uneven pot-hole laden street
- 4. Big drains provide tripping hazards for those on foot or bike
- 5. Recommend installing sidewalk
- 6. Recommend installing bicycle safe storm drains

Heritage Court toward Cooper Road

Photo 30: Heritage Court toward Cooper Road



- 1. Residential road connecting to Cooper Road
- 2. No sidewalks on either side of the street
- 3. Cracked, uneven pot-hole laden street
- 4. No stop bar
- 5. Recommend painting stop bar
- 6. Recommend installing sidewalks

Intersection of Heritage Court and Cooper Road

Photo 31: Intersection of Heritage Court and Cooper Road



- 1. Cracked, uneven asphalt
- 2. No crosswalk
- 3. No truncated domes
- 4. Recommend repairing sidewalk
- 5. Recommend painting high visibility crosswalk striping and installing truncated domes

Cooper Road towards Debra Court

Photo 32: Cooper Road towards Debra Court



- 1. Cracked, uneven sidewalk
- 2. Holes present tripping hazards
- 3. No curbs or other barrier to help shield pedestrians
- 4. Recommend repairing/re-paving sidewalk
- 5. Recommend installing curbs or bollards to create barrier

Cooper Road towards Terrill Road

Photo 33: Cooper Road towards Terrill Road



- 1. Narrow, uneven sidewalk
- 2. Leaves, twigs, mulch, dirt
- 3. Homes with driveways have landscaping that makes it difficult to see vehicles
- 4. Litter present on sidewalk
- 5. No barrier/separation of road and sidewalk
- 6. Recommend repairing/re-paving sidewalk
- 7. Recommend installing bollards or curbs to provide barrier between street and sidewalk
- 8. Recommend discussing property maintenance with owners in keeping sidewalks clear

Intersection of Cooper Road and Terrill Road

Photo 34: Intersection of Cooper Road and Terrill Road




- 1. Cooper Road and Terrill Road
- 2. Intersection has working pedestrian signals
- 3. Sidewalk ends on this side several yards down
- 4. Faded crosswalk
- 5. Faded street markings for drivers
- 6. No "School Zone" Sign
- 7. Drivers driving fast, trying to avoid stopping at red light
- 8. Recommend installing "School Zone" signs
- 9. Recommend re-striping high visibility crosswalk
- 10. Recommend re-painting street markings

Intersection of Cooper Road and Terrill Road

Photo 35: Intersection of Cooper Road and Terrill Road



- 1. Intersection has working pedestrian signals
- 2. Cracked, uneven asphalt in crosswalk
- 3. Very faded crosswalk striping
- 4. Recommend repairing/re-paving crosswalk
- 5. Recommend re-painting high visibility crosswalk



Map 7: Walkability Assessment of Route 4




Terrill Middle School



Route 4

Walking along Raritan Road

Photo 36: Walking along Raritan Road



- 1. Many sidewalks are cracked, broken, narrow and uneven asphalt that abruptly stop
- 2. Debris covers and narrows sidewalks
- 3. Utility poles and sign posts stick out as tripping hazards
- 4. Vegetation overgrown and unkempt, encroaching into sidewalks
- 5. Roads are very wide
- 6. Recommend repairing/re-paving existing sidewalks
- 7. Recommend addressing debris and vegetation overgrowth with owners
- 8. Recommend painting bike lanes in both directions

Intersection of Raritan Road and Black Birch Road

Photo 37: Intersection of Raritan Road and Black Birch Road



- 1. Cracked, uneven asphalt in crosswalk
- 2. No crosswalk striping
- 3. No truncated domes
- 4. No stop bar
- 5. No curbs
- 6. Wide turning radii
- 7. Recommend painting high visibility crosswalk and installing truncated domes
- 8. Recommend reducing turning radii by extending sidewalk, adding curbs

Intersection of Raritan Road and Green Hickory Hill

Photo 38: Intersection of Raritan Road and Green Hickory Hill



- 1. Sidewalk suddenly stops
- 2. Utility Pole in middle of path if sidewalk continued
- 3. No crosswalk striping
- 4. Truncated dome and curb ramp on far side are facing the wrong way
- 5. Near side has no curb ramp, no truncated dome, no sidewalk
- 6. Recommend painting high visibility crosswalk
- 7. Recommend fixing truncated dome and curb ramp direction
- 8. Recommend adding curb ramp, truncated dome and finishing sidewalk to curb

Walking Along Terrill Road


Photo 39: Walking Along Terrill Road




- 1. Cracked, broken, narrow, uneven, raised asphalt sidewalks
- 2. Trees roots have damaged sidewalks
- 3. Sidewalks stop randomly and begin again
- 4. Shoulders very wide
- 5. Recommend repairing/re-paving level sidewalks
- 6. Recommend utilizing some shoulder lane width and install bike lanes with signage

Intersection of Colonial Drive and Terrill Road

Photo 40: Intersection of Colonial Drive and Terrill Road



- 1. Intersection has truncated dome pads and curb ramps facing the wrong direction
- 2. Missing crosswalk
- 3. Missing stop bar
- 4. Cracked, uneven asphalt in what would be crosswalk area
- 5. Recommend repairing/re-paving crosswalk
- 6. Recommend painting crosswalk
- 7. Recommend fixing direction of truncated domes and curb ramps







Walking along Graymill Drive

Photo 41: Walking along Graymill Drive



Observations and Recommendations

- 1. No sidewalks
- 2. Wide street
- 3. Recommend installing sidewalks

Intersection of Graymill Drive and West Broad Street

Photo 42: Intersection of Graymill Drive and West Broad Street



- 1. Intersection has working pedestrian signals
- 2. Cracked, uneven asphalt in crosswalk
- 3. Very faded crosswalk striping; practically cannot see it
- 4. No sidewalk
- 5. No curb ramp or truncated dome on near side
- 6. Recommend repairing/re-paving crosswalk
- 7. Recommend adding sidewalks, truncated dome

Walking Along West Broad Street


Photo 43: Walking Along West Broad Street



- 1. Cracked, uneven asphalt sidewalks in need of repair
- 2. Recommend repairing/re-paving sidewalks

Intersection of Fenimore Drive and Martine Avenue

Photo 44: Intersection of Fenimore Drive and Martine Avenue



- 1. Missing stop bar
- 2. No crosswalk striping
- 3. No sidewalk, forcing residents to walk in street
- 4. Very wide street
- 5. Recommend painting high visibility crosswalk and stop bar
- 6. Recommend adding sidewalks

Intersection of Fenimore Drive and Essex Road

Photo 45: Intersection of Fenimore Drive and Essex Road



- 1. Cracked, uneven, pot hole ridden street
- 2. No sidewalks
- 3. No high visibility crosswalk
- 4. No curbs, curb ramps, or truncated domes
- 5. Recommend repairing/re-paving street
- 6. Recommend installing sidewalks, curbs, curb ramps, truncated domes
- 7. Recommend painting high visibility crosswalk

Bike Path Behind Terrill Middle School

Photo 46: Bike Path Behind Terrill Middle School



- 1. Rear bike path from Essex Road that leads to Terrill Middle School
- 2. Path is in disrepair, uneven, narrows, and riddled with holes
- 3. Edges of path are dirt covered, get muddy, and can make the journey unpleasant
- 4. Recommend repaving path and addressing issues of flooding/mudding

Bike Path Behind Terrill Middle School

Photo 46: Bike Path Behind Terrill Middle School



Observations and Recommendations

- 1. Rear bike path from Essex Road that leads to Terrill Middle School
- 2. Bikes are lined up along the fence
- 3. Recommend installing several bike racks

4. Action Plan & Recommendations

The Safe Routes to School Action Plan is organized into the "Five E's": Education, Encouragement, Enforcement, Engineering and Evaluation. Additionally, each element of the Action Plan considers two parameters – time and cost as shown below. Together, they comprise a set of directions to help the community prioritize their action steps to increase safety for students. The tables below identify preliminary recommendations specific to Terrill Middle School and its immediate area. To realize the full benefit of the SRTS program, it is suggested that this School Travel Plan be used to apply for SRTS grant funds to assist with implementing the action steps.

Timeframe Definition	Cost Definition
Short-term = less than 3 months	Low = Less than \$2,000
Mid-term = between 3 to 6 months	Medium = between \$2,000 and \$10,000
Long-term = longer than 6 months	High = more than \$10,000

1. Education: Programs to educate students, parents and the public about safe walking and biking

Education Actions	Responsibility	Time Frame	Cost
Circulate Travel Plan Report on school	Board of	Short-term, Mid-	Low
website	Education	term, Long-term	
Confirm School Zone signs adequately	Board of	Short-term, Mid-	Low
identify the school area	Education	term, Long-term	
Create and update Family Handbook that	School, School	Long-term	Low
defines arrival and dismissal procedures with	Liaison, PTO		
map and text that defines drop-off/pick-up			
areas, the rules and procedures for driving			
along local streets within school campus and			
school driveway			
Notify parents/guardians and school staff by	School	Long-term	Low
publishing information/updates in the			
Parent/Family Handbook, School Newsletters			
and on the school website			
Invite EZ Ride to help with bicycle and	School, EZ Ride	Short-term, Mid-	Low
pedestrian safety education with assemblies		term, Long-term	
or Bike Rodeos			
Integrate walking and safety education into	School, EZ Ride	Short-term, Mid-	Low
classroom curriculum		term, Long-term	
Leverage Social Media to spread awareness of	School Action	Short-term, Mid-	Low
school zone and enforcement activities	Team, PTA	term, Long-term	

Drop-off line instructions, help to	School, PTA,	Short-term, Mid-	Low
reduce length of car lines and conflicts	Principal	term, Long-term	
Cell phone free zone: In school, Outside	Principal	Short-term, Mid-	Low
during arrival and dismissal		term, Long-term	

2. Encouragement: Programs to encourage or promote walking and biking

Encouragement Actions	Responsibility	Time Frame	Cost
The town can pass a Complete Streets	Township	Mid-term	Low
Policy			
Hold a student poster or bookmark contest	School, EZ Ride	Short-term	Low
about Walking and Biking to school			
Circulate Time Radius Map and Travel Plan	VTC, EZ Ride, School	Short-term	Low
Report via the school website			
Host Bike/Walk to School Days throughout	School, PTA, School	Short-term, Mid-	Low
the school year	Liaison, EZ Ride	term, Long-term	
Participate in International Walk to School	School Action Team,	Short-term, Mid-	Low
Day in October, National Bike to School	PTA, EZ Ride	term, Long-term	
Day, and NJ Walk and Bike to School Day			
Utilize the school website to advance Safe	EZ Ride, School Tech	Mid-term, Long-	Low
Routes to School safety messages at least 1	Coordinator	term	
week in advance			
Establish and organize Bike	School, EZ Ride	Mid-term, Long-	Low
Trains/Walking School Buses to connect		term	
students and families who are already			
walking or are considering walking/biking			

3. Enforcement: Activities to improve safety and security for those walking and biking to school

Enforcement Actions	Responsibility	Time Frame	Cost
Conduct bicycle registration and helmet	School, Police	Short-term, Mid-	Low
giveaways at Back to School night		term, Long-term	
Investigate training Walking School Bus	School Liaison, Police	Mid-term, Long-	Low
volunteers		term	
Conduct speed studies along Terrill Road	Police	Short-term, Long-	Medium
and Raritan Road		term	
Ask police to setup electric signs that post	Police, School Liaison	Short-term, Long-	Low
drivers speeds and remind people to not		term	
speed as its school zone – twice a year			
Discuss property maintenance with owners	School, PTA, Police	Short-term, Long-	Low
to keep existing sidewalks free of debris,		term	

plants, trees, and brush so as to not impede			
pedestrians' journey			
Enforce the "No Parking" sign on Aberdeen	School, Police	Short-term, Long-	Low
Road behind Coles Elementary		term	
Pedestrian Decoy Operation – target	Police, Board of	Long-term	Low
unsafe drivers, especially during school	Education		
commute time			

4. Engineering: Infrastructure upgrades that improve walking and biking environment

Engineering Actions	Responsibility	Time Frame	Cost
Install sturdy state of the art bike racks	Twp. Engineering,	Mid-term, Long-	Medium
and skateboard racks near school's front	Police, School	term	
and rear entrances			
Post "School Zone" signs and paint	Twp. Engineering,	Mid-term, Long-	Low
"school zone" on roadways surrounding	Police	term	
the school			
Post signs and paint area on street to	Twp. Engineering,	Short-term, Mid-	Medium
define Bus and Car drop-off zones	Police	term, Long-term	
Investigate driveway and parking lot	Twp. Engineering,	Short-term, Mid-	High
circulation at school and enact measures	Police	term, Long-term	
for safety			
Paint or repaint high visibility crosswalks	Twp. Engineering,	Short-term, Mid-	High
at Aberdeen Road and Highlander Drive,	Police	term, Long-term	
Highlander Drive and Argyle Court,			
Highlander Drive and Clydesdale Road,			
Highlander Drive and Heather Lane,			
Heather Lane and Cooper Road, King			
Street and Martine Avenue, Tanglewood			
Lane and King Street, King Street and			
Terrill Road, Terrill Road and Cushing			
Road, Kevin Road by Coles Elementary,			
Heritage Court and Cooper Road, Cooper			
Road and Terrill Road, Raritan Road and			
Black Birch Road, Raritan Road and Green			
Hickory Hill, Colonial Drive and Terrill			
Road, Graymill Drive and West Broad			
Street, Fenimore Drive and Martine			
Avenue, Fenimore Drive and Essex Road			
Repair and repave sidewalks along Terrill	Twp. Engineering,	Short-term, Mid-	High
Road, Cooper Road, King Street, Kevin	Police	term, Long-term	
Road, Coles Elementary Bike Path, Terrill			
Middle School Back Bike Path, Coles			

	-		
Elementary Parking lot, Raritan Road,			
West Broad Street, Heather Lane, and			
Heritage Court			
Install sidewalks where missing along	Twp. Engineering,	Short-term, Mid-	High
Terrill Road, Cooper Road, Martine	Police	term, Long-term	
Avenue, Highlander Driver, Aberdeen			
Road, Raritan Road, Kevin Road, Graymill			
Drive, Fenimore Drive, Essex Road, West			
Broad Street, King Street			
Install curb ramp at Coles Elementary	Twp. Engineering,	Short-term, Mid-	Medium
Back Bike Path	Police	term, Long-term	
Installing new curb ramps, truncated	Twp. Engineering,	Short-term, Mid-	High
domes, along majority of the side roads	Police	term, Long-term	
such as Aberdeen Road and Highlander			
Drive, Highlander Drive and Argyle Court,			
Highlander Drive and Clydesdale Road,			
Highlander Drive and Heather Lane,			
Heather Lane and Cooper Road, King			
Street and Martine Avenue, Tanglewood			
Lane and King Street, Heritage Court and			
Cooper Road, Raritan Road and Black			
Birch Road, Raritan Road and Green			
Hickory Hill, Colonial Drive and Terrill			
Road, Graymill Drive and West Broad			
Street, Fenimore Drive and Essex Road			
Paint Bike Lanes or sharrows along	Twp. Engineering,	Short-term, Mid-	High
Raritan Road, Terrill Road, Cooper Road	Police	term, Long-term	
Investigate traffic speeds around the	Twp. Engineering,	Short-term, Mid-	Medium
school and post speed limit signs as traffic	Police	term, Long-term	
calming concepts			
Install School Zone signs that define the	Twp. Engineering,	Short-term, Mid-	Medium
school area; install signs with augmented	Police	term, Long-term	
flashing beacons			
	-		

5. Evaluation: Efforts to monitor and evaluate progress towards the achievement of SRTS goals

Evaluation Actions	Responsibility	Time Frame	Cost
The town can pass a Complete Streets	Township	Mid-term	Low
Policy			
Continue to conduct student travel tallies	School, EZ Ride	Short-term, Mid-	Low
to measure how effective the SRTS		term, Long-term	
program has been in increasing the			
number of students walking, biking or			
carpooling			
Improve communications between school	School Action Team,	Short-term, Mid-	Low
officials and families establishing a	PTA, School Tech	term, Long-term	
convenient mechanism to share	Coordinator		
information and get feedback			

Conclusion

Community priorities should include repairing, repaving, widening, and ensuring that current sidewalks are level and even. There is a need to install new sidewalks, add or fix curb ramps and truncated dome pads, and paint or repaint high visibility crosswalks and stop bars, paint bike lanes, and install bike parking in front of and behind Terrill Middle School.

The walkability audit demonstrated that Scotch Plains is an attractive community but it is not very walkable. The lack of sidewalks and crosswalks reduce safe spaces for students to travel. The measures that are recommended in this travel plan will improve the city's walkability, increase pedestrian safety, and encourage students and parents to walk or bike to school. Through increased use of active transportation, residents will make Scotch Plains a more appealing community by reducing air pollution and traffic congestion. Additionally, if more residents are able to safely walk and bicycle, they may be more active and healthy. EZ Ride is proud to work with the community to improve safety and bring SRTS programming to the schools. It is hoped this School Travel Plan report will be used to apply for an SRTS infrastructure grant or other DOT grants to make the intersections, sidewalks, and streets safer for students to walk and bike to Terrill Middle School.

Appendix A

How to Approach Residents Who Oppose Sidewalk Installation

What objections might homeowners make to installing sidewalks in their neighborhoods and how can I address these concerns?

Walking is the most recommended form of exercise. People are more likely to do it when the "gym" is just outside the door. Yet landowner objections sometimes result in disconnected sidewalk systems that make walking in neighborhoods or on work breaks difficult and/or dangerous.

Common concerns about sidewalks and potential answers to address them include:

Concern: Sidewalks are associated with urban settings and we live in a rural or suburban setting.

Answer: Roadways are part of urban, suburban, and rural settings. Few people would argue against streets being built in suburban or rural environments. A sidewalk is part of a complete street. Moreover, the majority of quaint, small towns sport sidewalks that provide freedom and mobility to young and old alike.

Concern: We'll lose established trees if we install sidewalks.

Answer: Sidewalks do not have to be linear. They can curve around trees. Does a neighborhood or community concerned about removing trees to install sidewalks apply the same logic to removing trees to build new homes, schools, and commercial buildings?

Concern: I don't want my neighbors walking near my house; that's an invasion of privacy. **Answer:** Walkers are the eyes and ears of a neighborhood. This can be a good thing if your house is on fire or you need help. Sidewalks and walking paths promote neighborliness and good health. Motorists drive by houses every day. Those who pull into residential driveways for one reason or another may get closer to a house than would a walker on a sidewalk.

Concern: Sidewalks are conveyer belts for crime, strangers, undesirables and renters.

Answer: Statistically, cars and trucks are the conveyance of choice for the perpetrators of home burglaries and assaults by strangers in a home. Streets convey all manners of people passed and to our homes, and there is little evidence to show that sidewalks increase the chance of crime.

Concern: I don't want to pay for a sidewalk.

Answer: In new development, sidewalks are typically required by the design standards of the local jurisdiction and should be paid for and installed by the developer of the property. Whether sidewalks actually appear is another question. If a developer waits until all the lots are built before installing sidewalks, this opens the door to homeowners objecting to a sidewalk in front of their home. Some communities pay half — or all — the cost of installing sidewalks, viewing sidewalks no differently than streets.

Concern: A sidewalk will reduce my property value.

Answer: Sidewalks seldom negatively affect property value unless they are in poor condition. The property value may actually increase for homes in walkable neighborhoods.

Concern: Snow removal is a problem for me; I don't want to (or can't) shovel snow.


Answer: Sidewalks save lives by keeping walkers, joggers, and children off busy roads. The Swedish believe cold fresh air is good for the immune system. Teenagers can earn extra money by shoveling your sidewalk. Perhaps the person who clears your driveway of snow could also shovel your walk.

Concern: Sidewalks are a sign of suburban sprawl in rural neighborhoods.

Answer: Where feasible to install and likely to be used, sidewalks in rural areas give children a place to walk to the school bus or to a friend's home for transportation and for healthy, daily physical activity. A lack of sidewalks has contributed to the sprawl of waistlines in the U.S.

Source: Pedestrian and Biking Information Center FAQ. Accessed: http://www.pedbikeinfo.org/data/faq_details.cfm?id=3456

Appendix B Typical Opportunities for Improvement



LONG CROSSING DISTANCES

Long crossing distances prolong the exposure time of pedestrians to motorists and make it difficult to see the pedestrian signal head on the other side of the road.



PEDESTRIAN OBSTRUCTIONS

Obstructions in the pedestrian right-of-way impede pedestrian movement and safety.



LACK OF CURB CUTS

Sidewalks without curb cuts are an obstacle to parents with baby carriages as well as people with disabilities.



POOR MAINTENANCE

Without maintenance pedestrians can trip, it can be a liability issue, and people with disabilities can have trouble negotiating the area.

Typical Bicycle/Pedestrian Treatments



SHARED-USE ROADWAY

Can be a safe for bicyclists when:

- Width is sufficient
- · Speeds are low
- · Traffic volumes are low



BICYCLE LANE

- Provides a safe and comfortable environment for bicyclists
- An area that is delineated, but not separated from the roadway
- Typically 4' wide with a bicycle stencil



SHARED USE PATH (TRAIL)

- Offers connections and opportunities not provided in the roadway system
- Can provide valuable connections and recreational opportunities
- Typically 8'-10' wide





OTHER FACILITIES

- Bicycle Lockers
- Bicycle Racks on Transit
- Bicycle Racks
- Bicycle Safety Programs

Typical Bicycle/Pedestrian Treatments



SIDEWALKS

- A portion of the road ROW for the preferential or exclusive use of pedestrians
- Typically at least 5' wide
- Should be free of obstructions along its width and 80" high



CROSSWALKS

- Provides a designated crossing point
- Helps provide more predictable pedestrian movements
- · Alerts drivers to pedestrian areas



SIGNAGE AND STRIPING

- Can help define pedestrian realm
- Provide visual cues for pedestrians and motorists
- Can augment other facilities



AMENITIES AND AESTHETICS

- Lets pedestrians know area was designed for their use
- Helps provide a safe and comfortable environment
- Helps provide sense of "place"

Typical Bicycle/Pedestrian Treatments



CURB EXTENSION

- Reduces Vehicle Speeds
- Reduces Pedestrian Crossing Distance
- Increases Pedestrian Visibility
- Protects Parking Area & Prevents Parking Close to Intersection



FULL CLOSURE

- Can be used to eliminate neighborhood cut-throughs
- Eliminates vehicular access
- Allows pedestrian and bicycle access and egress



MID-BLOCK CROSSING

- Reduces Vehicle Speeds
- Increases Pedestrians Visibility
- Reduces Pedestrian Crossing Distance
- Connects Pedestrian Generators



RAISED MEDIAN GATEWAY

- Provides Defined Entry
- · Provides Cue to a Transition Area
- Aesthetically Pleasing
- Provides Pedestrian Refuge
- Reduction in Vehicle Speeds

Typical Traffic Calming Devices



GATEWAY

- · Provides Defined Entry
- Provides Cue to a Transition Area
- Aesthetically Pleasing



CURB EXTENSION REDUCED TURNING

- Reduces Vehicle Speeds
- Reduces Pedestrian Crossing Distance
- Increases Pedestrian Visibility
- Protects Parking Area & Prevents Parking Close to Intersection



RAISED

- Reduces Vehicle Speeds
- Increases Pedestrians Visibility
- Reduces Pedestrian Crossing Distance
- Provides Pedestrian Refuge



BIKELANE

- Reduces Vehicle Speeds
- Produces Designated Lane for Bicyclists
- Provides Additional Buffer for Pedestrians

Typical Traffic Calming Devices



CURB EXTENSION

- Reduces Vehicle Speeds
- Reduces Pedestrian Crossing Distance
- Increases Pedestrian Visibility
- Protects Parking Area & Prevents Parking Close to Intersection



MEDIAN REFUGE

- Reduces Vehicle Speeds
- Reduces Pedestrian- Vehicle Conflict
- Reduces Pedestrian Crossing Distance
- Improves Aesthetics if wellmaintained



MID-BLOCK CROSSING

- Reduces Vehicle Speeds
- Increases Pedestrians Visibility
- Reduces Pedestrian Crossing Distance
- Connects Pedestrian Generators





Sidewalks and Access

- Simplifies Crossing Movement
- · Reinforces pedestrian priority
- Improves visibility
- Provides safe accessibility